

700 West Mineral Ave  
Littleton, CO 80120



*Network Disclosure Announcement No. 788*

Short Term Public Notice Under Rule 51.333(a)

**CenturyLink's(Qwest Communications) Internet address:**

<http://www.centurylink.com/disclosures/>

**Copper Retirements in Arizona, Iowa, Minnesota, Montana, and North Dakota.**

**First Implementation Date:** *April 30, 2017*

**Original Date Posted:** **April 22, 2016**

**Summary:**

Copper Retirements are necessary to respond to various factors in the Outside Plant, including road construction, maintenance problems, and growth accommodation. Replacement cables may be either copper or fiber. Specific information will be provided with each disclosure.

**Locations, Timing of  
Deployments & Interface  
Requirements:**

The following gives additional details on the copper retirement(s):

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	Replacing
AZ	McClintock TEMPAZMC	4-30-2017	N/A	N.067002	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	Replacing
AZ	Higley HGLYAZMA	4-30-2017	411615	N.044281	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
AZ	Tucson Cortaro TCSNAZCO	4-30-2017	3106	N.045426	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
IA	Altoona ALNAIACO	4-30-2017	220402 220403 141001 141002	N.067475 N.067481 N.067230	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	Replacing
MN	St. Cloud STCDMNT0	4-30-2017	410902	N.048193	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
MN	Cold Spring CLSPMNCB	4-30-2017	110302	N.019034	Raod construction in the area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
MN	Cottage Grove CTGVMNCG	4-30-2017	210604	N.030586	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	Replacing
MT	Bozeman BZMNMTMA	4-30-2017	230131	N.064735	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
ND	Dickinson DCSNDBC	4-30-2017	N/A	N.061595	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

**Additional Information:**

Any person desiring additional technical information in conjunction with this Disclosure can contact:

Abdennaceur Boudhaouia  
 Regulatory Compliance Director  
 303-707-8561  
[Jamal.Boudhaouia@CenturyLink.com](mailto:Jamal.Boudhaouia@CenturyLink.com)